

Andhra Pradesh State Road Transport Corporation Mechanical Engineering Department

Office of the VC & MD, Bus Bhavan, Hyderabad – 624.

No: OP2/462(1)/2007- MED


Circular No:11/2008-MED, dated 12th June 2008

Sub: <u>MAINTENANCE</u> – Introduction of Multi Layer Steel (MLS) Cylinder Head Gasket on Tata Vehicles – Reg.


M/s Tata Motors have informed through Service Circular No SC/2007/39, Nov'07 that they have introduced *MULTI LAYER STEEL (MLS) Cylinder Head Gasket* on all 697 vehicles in place of the earlier NON RETORQUABLE GASKET. The chassis break points on which this new gasket introduced are

- ➤ 373088 DSZ 209911 of Jamshedpur make
- > 373145 KSZ 741601 of Pune make

Unlike the earlier type gaskets, the MLS gasket is *provided with metallic layer* and is reusable. Hence, there is no need to replace the Cylinder head gasket with a new one during engine overhaul or for any other complaints where the cylinder head is removed. The same gasket can be used again. The visual difference between Asbestos Cylinder head gasket and the MLS Cylinder head gasket is shown hereunder.



MLS GASKET VICTOR REINZ – IMPORTED INDIGENOUS



ASBESTOS GASKET VICTOR REINZ -

The MLS Gasket is supplied by M/s VICTOR REINZ and its Part Number is 2525 0115 5339.

There is no change in Cylinder head tightening torque and procedure and this is also non-retorquable.

The Depot Managers and Maintenance incharges are advised to make note of the above modifications and propagate the message to all maintenance staff. It is also advised to *ensure that MLS Cylinder Head Gasket is not replaced* during Top-overhaul or for any reasons where the cylinder head is removed unless there is damage/ failure on the gasket.

EXECUTIVE DIRECTOR (E&IT)

To

All Depot Managers for necessary action.

Copy to : EDs(Zones) for information

Copy to : CCOS, CME(C&B) & CE(IT) for information

Copy to : All Dy.CMEs for necessary action.

Copy to: All Works Managers for necessary action

Copy to : All COS' for necessary action.

Copy to : All Principals, ZSTCs and TA/HPT for information.

Copy to: All Maintenance incharges for necessary action.

Copy to: Manuals section.