

# ANDHRA PRADESH STATE ROAD TRANSPORT CORPORATION



O/O the VC & MD,  
MSRD – HYDERABAD.

OP2/462(66)/2005-MED

## **Circular No.:15/2005:MED, Dated:30.11.2005.**

Sub: AIRLOCKS - Proper functioning of feed pump and condition of feed pump valves inspection during Sch-IV maintenance - Reg.

-000-

Instances have come to the notice that vehicles are failing enroute with Airlock problem due to defective feed pump or wornout /struck feed pump valves. There are no specific instructions regarding the periodicity of checking the functioning of feed pump and condition of the feed pump valves. This is resulting in on line failures.

**All the DMs are hereby advised to instruct the garage In-charges to check the functioning of feed pump and condition of the feed pump valves during every Sch-IV and replace if necessary.** However, feed pump strainer is to be cleaned during every Sch-II as usual. These instructions are to be strictly implemented with immediate effect and any failure on line in future due to defective feed pump or feed pump valves will be viewed seriously.

All the inspecting officers i.e., DVMs / Dy.CMEs / RMs shall ensure implementation of these instructions without fail.

**EXECUTIVE DIRECTOR(E)**

To

### **All the Depot Managers**

- Copy to : VC & MD for favour of information. ,
- Copy to : Director (V&S), ED(A), ED(O), ED(IT&MS), FA & CAO for information.
- Copy to : All EDs (ZVH&K, V&V, K&N for information.
- Copy to : All HODs for information.
- Copy to : All RMs for information & necessary action.
- Copy to : All DVMs for information & necessary action.
- Copy to : All DY.CMEs, WMs, COS' for information & necessary action.
- Copy to : All Principals of ZSTCs & TA/HPT for information.
- Copy to : All Maintenance incharge for similar action.
- Copy to : Training Officer/HO for necessary action