

ANDHRA PRADESH STATE ROAD TRANSPORT CORPORATION

MECHANIICAL ENGINEERING DEPARTMENT: BUS BHAVAN HYDERABAD - 500 624

NO:TL 6/293(11-T)/2008-MED

Dt. 28.03.2011

<u>Circular No. 07/2011 – MED dt. 28.03.2011</u>

Subject: VEHICELS – Procurement of fully built buses under JnNURM Scheme - Guidelines on warranty conditions - Issued - Reg.,

The Corporation has procured fully built semi-Low floor and Low-floor A/C, Non-A/C and CNG buses under JnNURM scheme for improving the transport facilities in the Metro City of Hyderabad / Secunderabad and Vijayawada, Visakhapatnam, Tirupathi cities.

The above buses are procured from M/s Ashok Leyland and M/s Tata Motors Ltd., as per the approved specifications and brands of units with warranty for a period of 3.00 lakh Kms or 36 months from the date of receipt of bus whichever is earlier. Generally as a policy the new vehicles are supplied with new Tyres and Batteries which are manufactured within six months from the date of supply. But in view of certain administrative reasons some of the vehicles are accepted with tyres and Batteries which are having manufacturing date beyond one year from the date of receipt for which the competent authority has accorded approval. The details of vehicles fitted with these tyres and Batteries with numbers are mentioned in the statement enclosed.

M/s Ashok Leyland and M/s Tata Motors Ltd., have agreed to extend warranty for these tyres and Batteries as follows:

- 1. The Warranty for any manufacturing defect will be valid for one year or one lakh Kms which ever is earlier from the date of delivery of these buses to the Corporation.
- 2. The Warranty will be handled directly by M/s Ashok Leyland and M/s Tata Motors Ltd through dealers or authorised service stations.
- 3. The Warranty will be on pro-rata basis.

The tyre history cards and battery unit cards supplied along with these new vehicles are being endorsed to this effect. Any such warranty claims shall be referred to MED / Bus Bhavan for settlement.

Therefore, all the Depot Managers of these regions are hereby instructed to note the above and claim warranty if any accordingly.

All the Dy. CMEs / RMs are advised to oversee the implementation of Circular Instructions.

VICE CHAIRMAN & MANAGING DIRECTOR

Encl: As above

То

The Depot Managers of GHZ, VJA, VSP and TPT Regions

STATEMENT OF VEHICLES FITTED WITH TYRES & BATTERIES HAVING
ONE YEAR AND ABOVE MANUFACTURING DATE

01	1	BATTERIES			· · · · · · · · · · · · · · · · · · ·
SL.	1	TA/	VEH.NO	TVDE	DEP
No.	REGN	AV		TYPE	DEP
		No			
	HCR		11Z 7207	M.EXP	MSR
	HCR	TJ0910148	11Z 6496	M.EXP	MSR
	HCR	TJLD091076	11Z 7039	M.DLX	HYT
	SCR	TJLD091006	11Z 7127	M.DLX	BHE
	HCR	TJLD091038	11Z 7129	M.DLX	DSN
	SCR	.FJLD09109	11Z 7130	M.DLX	BHE
	SCR	TJLD091010	11Z 7131	M.DLX	BHE
	HCR	TJLD091066	11Z 7132	M.DLX	HYT
	SCR	TJLD091013	11Z 7133	M.DLX	BHE
10		TJLD09101	11Z 7134	M.DLX	BHE
11		TJLD091015	11Z 7135	M.DLX	BHE
12	-4	TJLD091080	11Z 7136	M.DLX	RNG
13		TJLD09102	11Z 7137	M.DLX	DSN
	SCR	TJLD091012	11Z 7138	M.DLX	BHE
1:		TJLD091077	11Z 7139	M.DLX	RNG
16		TJLD091051	11Z 7140	M.DLX	DSN
17	-4	TJLD09103	11Z 7141	M.DLX	BHE
18		TJLD09103	11Z 7142	M.DLX	DSN
19		TJLD091042	11Z 7143	M.DLX	BHE
20		TJLD091079	11Z 7144	M.DLX	НҮТ
2	,,,,,,,,,,,,	TJLD091014	11Z 7145	M.DLX	BHE
2		TJLD091041	11Z 7146	M.DLX	DSN
23	. j	TJLD091059	11Z 7147	M.DLX	НҮТ
		TJLD091039	11Z 7148	M.DLX	BH
24 25		TJLD091043	11Z 7149	M.DLX	BH
20		TJLD091043	11Z 7150	M.DLX	НҮТ
	HCR	TJLD091007	11Z 7151	M.DLX	DSN
	-4	TJLD091020	****	M.DLX	BH
2		TJLD091069	11Z 7152 11Z 7153	M.DLX	RNG
3	-4	TJLD091009	11Z 7154	M.DLX	HYT
3		TJLD091090	11Z 7155	M.DLX	BH
32		TJLD091008	11Z 7156	M.DLX	BHE
3	-1	TJLD091007	11Z 7229	M.DLX	DSN
3.		TJLD091004	11Z 7230	M.DLX	RNO
3		TJLD0910091	11Z 7230	M.DLX	HYT
3(TJLD0910091	11Z 7232	M.DLX	HYT
3	-4	TJLD091088	11Z 7232	M.DLX	НҮТ
3		TJLD091088	11Z 7235	M.DLX	НҮТ
39		TJLD091032	11Z 7236	M.DLX	BH
4(TJLD091030	11Z 7230	M.DLX	RNO
		TJLD091063	11Z 7237	M.DLX	BHE
4		TJLD091047	11Z 7230	M.DLX	RNG
4:		TJLD091018	11Z 7230	M.DLX	BHE
4	- 4	TJLD091018	11Z 7240	M.DLX	HYT
ı 444	t nuk	ניבטן פֿטלדוניו	114/441	MI-DLA	

		BATTERIES	SUPPLIED E	BY M/S IML		
CI TA/ VEH.NO						
No.	REGN	AV		TYPE	DEPOT	
140.	INLOW					
 		. No				
46	HCR	TJLD091053	11Z 7243	M.DLX	DSNR	
47		TJLD091046	11Z 7245	M.DLX	BHEL	
48		TJLD091022	11Z.7246	M.DLX	BHEL	
		TJLD091027	11Z 7247	M.DLX	DSNR	
49		TJLD091045	11Z 7248	M.DLX	BHEL	
50		TJLD091032	11Z 7249	M.DLX	HYT-1	
51		TJLD091019	11Z 7250	M.DLX	RNG-2	
52	<u> </u>	TJLD0910184	11Z 7251	M.DLX	RNG-2	
53			11Z 7252	M.DLX	DSNR	
54	4 <u></u>	TJLD091023		M.DLX	BHEL	
55			11Z 7254	M.DLX	HYT-1	
56		TJLD091061	11Z 7255	M.DLX	BHEL	
57		TJLD091023	******	M.DLX	DSNR	
58		TJLD091039	11Z 7257	M.DLX	HYT-1	
59		TJLD091082		M.DLX	RNG-2	
60	. <u> </u>	TJLD091074	11Z 7258		DSNR	
61		TJLD091040	112 7238		HYT-1	
62			11Z 7260	M.DLX	HYT-1	
63		TJLD091075	11Z 7261	M.DLX	DSNR	
64		TJLD091050			HYT-1	
6		TJLD091058			DSNR	
6	_46	TJLD091034	11Z 7263		RNG-2	
6	_1	TJLD091073		M.DLX M.DLX	HYT-1	
6	8 HCR	TJLD091054			RNG-2	
6	9 SCR	TJLD091068	11Z 7266	**************	DSNR	
[7	0: HCR	TJLD091031	11Z 7267		MSRD-2	
7	1 HCR	TJ0910478	11Z 7268		DSNR	
7	2 HCR	TJLD091057	11Z 7269	M.DLX	HYT-1	
7	3 HCR	TJLDAC09101	1: 11Z 72/0	M.DLX AC	BHEL	
[7	4 SCR		11Z 7272		DSNR	
[7	5 HCR	TJLD091049			HYT-1	
7	6 HCR	TJLDAC09100	9 11Z 7274	M.DLX AC	HYT-1	
7	7 HCR	TJLD091063	11Z 7275	M.DLX	BHEL	
7.7	8 SCR	TJLDAC0910			HYT-1	
7	9 HCR	TJLDAC09101			1	
1.5	O HCR	TJLDAC09101	4 11Z 7278	M.DLX AC	HYT-1	
1.5	SCR	TJLDAC09101			RNG-2	
178	E HCR	TJLDAC09101	8: 11Z 7280	M.DLX AC	DSNR	
	3 HCR	TJ0910476	11Z 7282		MSRD-1	
	HCR	TJLD091048	11Z 7283	M.DLX	DSNR	
L	5 SCR	TJLDAC0910	1: 11Z 7284	M.DLX AC	BHEL	
.	B6: HCR	TJLDAC0910	10: 11Z 7285	M.DLX AC	HYT-1	
L - 4	87 HCR		08 11Z 7286	M.DLX AC	HYT-1	
L	88 SCR			M.DLX	BHEL	
	89 HCF			M.DLX AC	HCU	
	90: SCF		2 11Z 7289		RNG-2	

Г	STATEM	MENT SHOWING	THE ONE	YEAR ABOVE	TYRES AND
				BY M/S TML	
SL.		TA/	VEH.NO		
No.	REGN	AV		TYPE	DEPOT
			-		
		No			
91	HCR	TJ0910479	11Z 7290	M.EXP	MSRD-1
92		TJLDAC091016	A	M.DLX.AC	RNG-2
93		TJLD091021	11Z 7293	M.DLX	BHEL
94		TJLD091065	11Z 7294	M.DLX	HYT-1
95		TJLD091035	11Z 7295	M.DLX	DSNR
96		TJ0910475	11Z 7296	M.EXP	MSRD-2
97		TJLD091044	11Z 7297	M.DLX	BHEL
98		TJ0910477	11Z 7298	M.EXP	MSRD-1
99		TJ0910473	11Z 7300	M.EXP	
4				~~~~~~~~~~~~~~~	MSRD-1
100	~~~~~~~	TJLD091017	11Z 7301	M.DLX	BHEL
101	HCR	TJLD091060 TJLD091028	11Z 7302	M.DLX	HYT-1
102	HCR		11Z 7303	M.DLX	DSNR
103	HCR	TJLD091062	11Z 7304	M.DLX	HYT-1
104		TJLDAC091012		M.DLX AC	HYT-1
105	HCR	TJLDAC091013		M.DLX AC	HYT-1
106	HCR	TJLDAC09104	11Z 7307	M.DLX AC	DSNR
107	SCR	TJLD091020	11Z 7308	CITY BUS	BHEL
108	HCR	TJLD091071	11Z 7310	M.DLX	HYT-1
109	SCR	TJLD091070	11Z 7311	M.DLX	RNG-2
110	HCR	TJ0910474	11Z 7312	M.EXP	MSRD-2
111	SCR	TJLDAC09106	11Z 7313	M.DLX AC	BHEL
112	HCR	TJLD091037	11Z 7314	CITY BUS	DSNR
113	SCR	TJLDAC09102	11Z 7315	M.DLX AC	BHEL
114	HCR	TJLD091086	11Z 7389	M.DLX	HYT-1
115:	HCR :	TJ0910483	11Z 7390 ;	M.EXP	MSRD-2
116	SCR	TJLDAC09105	11Z 7391 ;	M.DLX AC	BHEL
117	HCR	TJ0910481	11Z 7392	M.EXP	MSRD-2
118	HCR	TJ0910484	11Z 7393	M.EXP	MSRD-2
119	HCR	TJLD091087	11Z 7425	M.DLX	HYT-1
120		TJLDAC091028	11Z 7457	M.DLX AC	RNG-2
121	HCR :	TJLDAC091029	11Z 7459	M.DLX AC	HCU
122		TJLDAC091021	11Z 7461 :	M.DLX AC	BHEL
123	HCR :	TJLDAC091023	11Z 7462	M.DLX AC	HCU
124		TJLDAC091025		M.DLX AC	HCU
125	HCR	TJLDAC091022	11Z 7464	M.DLX AC	HCU
126	SCR	TJLDAC091020	11Z 7465	M.DLX AC	BHEL
127	HCR	TJLDAC091024	11Z 7466	M.DLX AC	HCU
128	SCR	TJLDAC091027		M.DLX AC	RNG-2
129	HCR ;	TJLD091089	11Z 7468	M.DLX	HYT-1
130		TJLDAC091026	11Z 7640 :	M.DLX AC	HCU
131	VSP :	TJ09100379	11Z 6951	M.EXP	MDP
132	VSP :	TJ09100409	11Z 7033	M.EXP	SML
133	VSP	TJ09100393	11Z 7009	M.EXP	WLT
134	VSP	TJ09100402	11Z 7007	M.EXP	WLT
135	HCR	TJ09100297	11Z 6668	M.EXP	UPL
				141 // .	WI L

STATEMENT SHOWING THE ONE YEAR ABOVE TYRES AND BATTERIES SUPPLIED BY M/S TML						
SL.		TAV	VEH.NO	DI WILC IML	 	
No.	REGN	AV		TYPE	DEPOT	
				111.	DEPUT	
		No				
136	!	TJLDAC091019	11Z 7458	M.DLX AC		
137	! !	TJLDAC090103		M.DLX AC		
138		TJLDAC091031	, · · · - · ·	M.DLX AC		
139		TJLD091092	11Z 7508	M.DLX		
140		TJLD091093	11Z 7496	M.DLX	· · · · · · · · · · · · · · · · · · ·	
141		TJLD091094	11Z 7500	M.DLX		
142		TJLD091095	11Z 7501	M.DLX		
143		TJLD091096	11Z 7510	M.DLX	· · · · · · · · · · · · · · · · · · ·	
144		TJLD091097	11Z 7507	M.DLX		
145	· · · · · · · · · · · · ·	TJLCAC091001		M.DLX AC	·····	
146		TJLAC091002	11Z 7520	M.DLX AC	7 	
147		TJLCAC091003	11Z 7502	M.DLX AC		
148		TJLAC091004	11Z 7514	M.DLX AC		
149	i	TJLCAC091005		M.DLX AC		
150		TJLAC091006	11Z 7505	M.DLX AC		
151		TJLCAC091007	11Z 7512			
152		TJLAC091008	11Z 7494	M.DLX AC		
153		TJLC0901001	11Z 7504	M.DLX AC		
154		TJLC0901002	11Z 7497	M.DLX	·	
155:		TJLC0901003	11Z 7515	M.DLX		
156:		TJLC0901004	11Z 7513	M.DLX		
157		TJLC0901005	11Z 7529 11Z 7521	M.DLX	·	
158	<u>-</u>	TJLC0901006	11Z 7538	M.DLX		
159:		TJLC0901008		M.DLX		
160		TJLC0901007	11Z 7544	M.DLX		
161			11Z 7543	M.DLX		
162	<u>-</u>	TJLC0901009	11Z 7546	M.DLX		
163	,	TJLC0901010	11Z 7527	M.DLX		
164:		TJLC0901011	11Z 7509	M.DLX		
165	+	TJLC0901012	11Z 7542	M.DLX		
166		TJLC0901013	11Z 7545	M.DLX		
167:		TJLC0901014		M.DLX		
168:		TJLC0901015	11Z 7541	M.DLX		
169		TJLC0901016	11Z 7523	M.DLX		
170		TJLC0901017	11Z 7537	M.DLX		
		TJLC0901018	11Z 7522	M.DLX	•	
171		TJLC0901019	11Z 7531	M.DLX		
172	<u> </u>	TJLC0901020	11Z 7536	M.DLX		
173		TJLC0901021	11Z 7534	M.DLX		
174		TJLC0901022	11Z 7532	M.DLX		
175		TJLC0901024	11Z 7517	M.DLX		
176		TJLC0901025	11Z 7513	M.DLX		
177		TJLC0901026	11Z 7547	M.DLX		
78		TJLC0901027	11Z 7550	M.DLX	· · · · · · · · · · · · · · · · · · ·	