

ANDHRA PRADESH STATE ROAD TRANSPORT CORPORATION

Office of the Managing Director,
RTC House, PNBS, Vijayawada.

No.P1/255(01)/2017-PO-I

CIRCULAR No. 05 /2017-PD DATED: 19.02.2017

SUB: ACCIDENTS IN GARAGES: Driving by unauthorised Apprentices and outsourced personnel in garages – Instructions not to allow such unauthorised driving of Corporation Vehicles – Issued - Reg.

- REF: 1. Circular No.PD-106/99, dated 12.11.1999
2. Circular No.PD-38/2006, dated 09.09.2006
3. Joint PD & MED Circular No.22/2007, dt. 25.04.2007
4. Joint PD & MED Circular No.20/2010, dt. 24.04.2010

>><<

Time and again instructions were issued on the procedure to be followed for outsourcing Activities of Shramiks in the garages. The Shramiks engaged through outsourcing activity shall not be permitted to drive the vehicles in the garage premises either for parking or other purpose in the garage.

Similarly, while directing the ITI Apprentices to under go practical training at Depots, it was clearly mentioned in the conditions of allotment that the ITI Apprentices are not permitted to drive any vehicle of the Corporation.

By allowing inexperienced ITI Apprentice to drive the vehicles in the garage premises, there is every possibility of occurrence of accidents.

In the recent past certain incidents of accidents occurred in the Depot garage premises while the vehicle were driven by inexperienced outsourcing Shramiks or ITI Apprentices.

In this regard, all the Unit Officers are hereby instructed not to allow any ITI Apprentice or outsourcing Shramiks to drive the vehicle in the garage premises. The valid Driving License holders meant for parking duties are only permitted to drive the vehicles in the garage premises.

All the Depot Managers and Mechanical In-charges are instructed to be more careful and permit only permanent employees with valid license shall be assigned parking driver duty to drive the vehicles in the garages for maintenance and parking purposes.

Malabo
VICE CHAIRMAN &
MANAGING DIRECTOR 19/2

[P T O]