0/0 General Manager Msrd Hyderabad - 20 Dt 17 6 82

No TR 3/642/1979

CIRCULAR NO 12/82/MED DT 17-6-82

Sub Instructions issued regarding preparation of makewise analysis of Tread Rubber by the TRS of the area - Reg

Ref No TR 4/240 (1 5)/78 of 1 FEB 79

In partial modification to clause 2 of the above referred Circular the tyres which have given full Service and scrapped due to worn smooth condition should be accounted for the analysis irrespective of whether it has given the expected mileage or not

The tyres which have given less than 10 000 KMs due to poor quality of tread rubber should also be accounted for analysis

The tyres which have rapid wear due to over - inflation under inflation mis-matching mechanical defects carcos failures (concussions) process failures etc and given less than 10 000 KMs should not be taken for analysis

Except for the above modification the other conditions mentioned in the circular shall remain unchanged

Please acknowledge

SD/-

CHIEF MECHANICAL ENGINEER

cc to RMs/CAO/Dy CAO/WM/AII AME (Tyres)

//attested//

Sd/-

Dy Chief Mechanical Engineer

(0) True Copy

//attested//

ACCOUNTS OFFICER (TA & I)